

2331 Topaz Drive, Hatfield, PA 19440 TEL: 800-219-9095 • FAX: 800-219-9096

Sold TO Safety Sentry Inc. 5415 Contrary Creek Rd. Granbury, TX 76048 SHIP TO Safety Sentry Inc. 5415 Contrary Creek Rd. Granbury, TX 76048 ATTN: Karl Pratt

CERTIFICATION DATE 6/24/2009

Certified Test Report

SSI018-09-06-18611-2

SHIP VIA FAX AND UPS

DESCRIPTION

Quantity:1Description:Model SS350 HD Bulldog

A Tensile test was performed on the submitted Test Specimen in accordance with Customer's Instructions with the following results:

	TENSILE	YIELD (.2%)	ELONGATION
	<u>STRENGTH</u>	<u>STRENGTH</u>	(IN 1")
TUAL	61.0 KSI (61,000 PSI)	48.2 KSI (48,200 PSI)	39%

The services performed above were done in accordance with LTI's Quality System Program Manual Revision 18 dated 7/27/07 and ISO/IEC 17025. These results relate only to the items tested and this report shall not be reproduced, except in full, without the written approval of Laboratory Testing, Inc. L.T.I. is accredited by PRI to ISO17025 and by Nadcap for NDT and Materials Testing for the test methods and specific services as listed in the Scopes of Accreditation available at www.labtesting.com and www.eAuditNet.com. The results reported on this test report represent the actual attributes of the material tested and indicate full compliance with all applicable specification and contract requirements.

MERCURY CONTAMINATION: During the testing and inspection, the product did not come in direct contact with mercury or any of its compounds nor with any mercury containing devices employing a single boundary of containment.

AC.

NOTE: The recording of false, fictitious or fraudulent statements or entries on this document may be punishable as a felony under Federal Statutes.

Sherri L. Scheifele QA Specialist

Sherri & Scheifele By:

Authorized Signature



Materials Testing Laboratory Nondestructive Testing

CUSTOMER P.O. CHECK